

DTMF Tone Timeout feature is added. [2-161](#)

Override Attendant VMID feature is added. [3-26](#)

PRI Call Pair Assignment feature is added. [2-284](#)

Off-Net Forward CLID Information feature is added. [2-32](#)

Off-Net Forward Redirect feature is added. [2-38](#)

Alternate Public IP Address Assignment feature is added. [D-39](#)

Flash 50/51, Pg C, Button #11 is modified to add an option to allow the use of any address to access the system.
[D-28](#)

Flash 50/51, Pg B, Button #7 is modified to add an option to allow intercom calls in the School Zone feature.
[2-298](#)

Flash 22, Button #9 is added to allow for Day, Night, & Special “Day of the Week Programming”.
[2-265](#)

Flash 43, Button #13 is added to allow for DISA based on DID route over T1/PRI/DID.
[2-136](#)

Flash 20, Button #1 - The DISA Access Code is changed from a 3-digit code to now allow any number from 0-9999999 for better security.
[2-136](#)

Flash 50/51, Pg A, Button # 9 is now a button that has 2 roles - enables OHVO for keysets & allocates a VOIP path to IP-24DH and IP7000-series phones so that the IP phones can get pages and background music.
[2-267](#)

Flash 06, Button #17 is added to provide disconnect call supervision on speakerphone calls.
[2-305](#)

Flash 06, Button #6 is added to control the ability of station-to-station calls between tenant groups.
[2-353](#)

A Macro Buttons feature is added. [2-251](#)

Flash 50/51, Pg D, Button #10 is added to allow programming of the fixed MSG button to be used either as the MSG button or as a VM access button.
[2-253](#)

Flash 50/51, Pg B, Button #3, “Station Night COS”, is deleted and Flash 50/51, Pg B, Button #2 is modified to allow Station Day, Night, & Special COS values.
[2-70](#) & [2-11](#)

Flash 60, Button #8, “Secondary Agents”, and feature codes 581 & 582 are deleted. Flash 60, Button #7, Agent Assignments”, is modified to include a priority code. The ACD feature is modified to allow an agent to simultaneously be logged into 5 ACD groups.
[4-25](#)

Flash 43, Button #14 is added to allow Distinctive Ring Tones for DID routes. [2-150](#)

The Trouble Notification feature is enhanced with a feature code that allows a user the option to bypass timers and immediately notify “trouble notification stations” of a problem.

[2-368](#)

The ACD Overflow Timer range is increased from 000-600 to 0000-3600. [4-23](#)

Flash 45, Pg A, Button #15 is added to provide the ability to set the ISDN type on PRI facilities.

[2-218](#)

Flash 50/51, Pg D, Button #11 is added to identify selected stations whose ICLID Call Data is saved into the system ICLID Call Management Tables. The Volume Up/Down buttons are now used to scroll through entries in ICLID Call Management Tables.

[A-24](#) & [3-24](#)

Flash 17, “Discovery Desktop IP Attendant Station Assignments” is added. [2-148](#)